ಬೃಹತ್ ಬೆಂಗಳೂರು ನಗರಾಭಿವೃದ್ಧಿ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	15	T Dasarahalli
Street ID	**Street Name**	**Significant Landmark**
W0072, W0061, W0067, W0057, W0060, W0080	NA, Om Shakthi Lyt 7th Crs, 13th Crs	GANESH SAW MILL
Segment No.	**Total Length (m)**	
15/C-W0072/S024501	190.44	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	190.44	77.511073	13.044973	77.512192	13.045559	W0057	W0065

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
IMPROVEMENTS AND CONSTRUCTIONOF CC ROAD AND DRAIN AT MAHESHWARI ROAD	1500000	2015
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Others	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	CC ROAD AND DRAIN	15-15-000022
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/307/2014-2015	25/03/2015	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		1473005.00
Phone No.	**E-Mail ID**	
8970389692		

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Field Inspection Details

Number of Trees	Any Other Information	Name
0		venkatesh

Date of Inspection	Remarks
29/02/2016	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDDEGOUDA	29/02/2016	30/03/2016	COMPLETED
EE	JOGI SIDDEGOUDA	29/02/2016	30/03/2016	COMPLETED
AEE	RANGASWAMY	29/02/2016	30/03/2016	COMPLETED
AE	VENKATESH	29/02/2016	30/03/2016	COMPLETED
AE	VENKATESH	29/02/2016	30/03/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0072, W0061, W0067, W0057,